

TOWN OF STETTLER

<u>Prepared by:</u>	Engineering & Waterworks Department	<u>Number:</u>	XV-2(c)
<u>Adopted by:</u>	Town of Stettler Council	<u>Previous Policy:</u>	N/A
		<u>Original Policy:</u>	N/A
		<u>Current Policy:</u>	1999 02 16

Title: **Guidelines For Camera Inspection of Sanitary Service Lines on Private Property**

Purpose: To establish guidelines for the camera inspection of sanitary service lines where a possible blockage or restriction is suspected within the pipe.

Policy Statement:

- a) Property owners who request a camera inspection of their sanitary service line will be referred to a private contractor.
- b) If a plumber suspects a blockage or restriction within the pipe on the Town's side of a sanitary service line the Town will camera the service line.
- c) If a plumber suspects a blockage or restriction within the pipe on the property owners side of a sanitary service line and would like to have it inspected they should have a private contractor camera the service line.
- d) If the blockage or restriction within the pipe is found to be on the property owners side, the property owner will pay the full cost of the camera inspection.
- e) If the blockage or restriction within the pipe is found to occur on both the Town's side and the property owners side of the property line, the property owner will pay one half the current rate.